24V (5:1) motor for firefighting monitors FireFox and StreamMaster - repair kit



24V motor 35780095 for firefighting monitors AKRON FireFox (3463) and StreamMaster I (3578, 3579 and 3598).

All spare parts and accessories AKRON® are available from **MMF Protection et Sécurité**. Rely on an authorized AKRON dealer / repair center!

Need advice or have a specific request? Just call us!

- by telephone on 04 78 00 00 25

- by e-mail at sav@mMF.fr