

Inlet elbow repair pack for StreamMaster 3578 and 3579



Repair pack for inlet elbow (elbow 121570 + magnet 731081) for monitor StreamMaster AKRON®

- Suitable only for monitors StreamMaster 3578 and 3579.

All AKRON® spare parts are available from **MMF Protection et Sécurité** all spare parts are available from the brand's authorized dealers and repair centers.

Need advice or have a specific request? Just call us!

- by telephone on [04 78 00 00 25](tel:0478000025)

- by e-mail at sav@mmf.fr